Am An GEO CONSULTANT

NAGARAJ MOKASHI, MSc.,
GEOLOGIST

Mobile : 94483 13401
e-mail : ngmokashi@rediffmail.com
am.an4geoconsultant@gmailcom

Ramjyothi Nagar, R.V.College Post, Bangalore - 560 059.

To,

Date : 10/4/17.

GEO-TECHNICAL SURVEY REPORT
(Ground Water Exploration)

Sir / Madam,

As per your work order/request Geo-Hydrological / Geo-physical Survey carried out in your land / site belonging ..Yelahanka.. city/village ..Balavalingeppa Layout..Dated on ..10/4/17..in order to assess the ground water potential of the area for drinking / irrigation / industrial purposes.

The area inspected has a slope towards ..N/S.. marked by ..Hard.. Soil, uneven topography hydrogeological features are found to be favourable / not favourable for ground water extraction. Geology of the area is marked by ..Rock.. rock.

SOURCES EXTRACTED :

(I) Betwen ..200-280 FT.. ft/mtrs. (II) ..360 - 430 FT.. ft/mtrs.

(III) ..800 - 950 FT.. ft/mtrs.

From the study of the above field observation, Investigation results, a borewell VES drilling ..950 FT..to app depth of ..980 FT.. ft/mtrs. Below the ground level, casing pipe required be to app depth of ..130 FT..ft/mtrs.
Approx, yield expected may be around ..4800..GPH.

Suggested to drill 4 $\frac{1}{2}$" / 6 $\frac{1}{2}$" dia Borewell.

****

NOTE : Although the best site for drilling has been suggested, no guarantee of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the site recommended being a failure in any form.

(NAGARAJ MOKASHI)

Save Water

SAVE ENVIRONMENT **ADOPT RAINWATER HARVESTING**

Services : Ground Water location by geo-hydrological, geophysical and divining methods, Drilling advisors and supervision. Rain Water harvesting, water shed management, Quarry operations, Planning, Water testing, Soil Testing & Surveying.

BOREWELL
COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 333

Date : 12/4/17

1. Customer's Name and Address with Telephone No. : AEE, Yelahanka Satellite Sub Division, Yelahanka New Town, Banglore-64.

2. Well Location : Basavalingappa Layout near Sumudaya Bhavana

3. Total Well Depth / Drilled in Ft. : 1085 Ft

4. Casing Erected in Ft. : 125 Ft

5. Water Struck at the Depth of : 998 Ft

6. Total Yield (Measuring method "V" Norch : 2½" / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear ✓

8. At the Depth of : 998 Ft

9. Recommended to use Jet Pump / Air Compressor / Submersible ✓ /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

AE W3

Party's Signature

Manager / Proprietor